

Before recycling

It is always recommended to reuse or repair before recycling, to prolong the use-phase of the product. If the product should be recycled, please use the following instructions.

Overview of materials

The table below shows the different materials used for production of COAT.

WOOD	Ash
PLASTIC RING	POM
METAL RING	Aluminium, steel or brass
PINOL SCREWS	Galvanized steel

Recycling instructions

Lift the metal ring upwards to remove it. Unscrew the pinol screws in the POM ring. Remove the POM ring.

The materials are sorted and recycled using the instructions at the recycling facility.