

Coefficients de correction (:) $f_1 = E/E50$ ($n=1,3$)

		Tr ($^{\circ}$ C)										
		Ta ($^{\circ}$ C)	40	45	50	55	60	65	70	75	80	85
Td ($^{\circ}$ C)	70	24	0.54	0.59	0.65	0.71	0.77	0.83	0.90	0.96	1.03	1.09
	70	22	0.58	0.64	0.70	0.76	0.82	0.88	0.95	1.01	1.08	1.15
	70	20	0.63	0.69	0.75	0.81	0.87	0.94	1.00	1.07	1.13	1.20
	70	18	0.68	0.74	0.80	0.86	0.92	0.99	1.05	1.12	1.19	1.25
	70	16	0.72	0.78	0.85	0.91	0.97	1.04	1.11	1.17	1.24	1.31
	85	24	0.71	0.77	0.83	0.90	0.96	1.03	1.09	1.16	1.23	
	85	22	0.76	0.82	0.88	0.95	1.01	1.08	1.15	1.21	1.28	
	85	20	0.81	0.87	0.94	1.00	1.07	1.13	1.20	1.27	1.34	
	85	18	0.86	0.92	0.99	1.05	1.12	1.19	1.25	1.32	1.39	
	85	16	0.91	0.97	1.04	1.11	1.17	1.24	1.31	1.38	1.45	
Td ($^{\circ}$ C)	80	24	0.65	0.71	0.77	0.83	0.90	0.96	1.03	1.09		
	80	22	0.70	0.76	0.82	0.88	0.95	1.01	1.08	1.15		
	80	19	0.77	0.83	0.90	0.96	1.03	1.09	1.16	1.23		
	80	18	0.80	0.86	0.92	0.99	1.05	1.12	1.19	1.25		
	80	16	0.85	0.91	0.97	1.04	1.11	1.17	1.24	1.31		
Td ($^{\circ}$ C)	75	24	0.59	0.65	0.71	0.77	0.83	0.90	0.96			
	75	22	0.64	0.70	0.76	0.82	0.88	0.95	1.01			
	75	20	0.69	0.75	0.81	0.87	0.94	1.00	1.07			
	75	18	0.74	0.80	0.86	0.92	0.99	1.05	1.12			
	75	16	0.78	0.85	0.91	0.97	1.04	1.11	1.17			
Td ($^{\circ}$ C)	70	24	0.54	0.59	0.65	0.71	0.77	0.83				
	70	22	0.58	0.64	0.70	0.76	0.82	0.88				
	70	20	0.63	0.69	0.75	0.81	0.87	0.94				
	70	18	0.68	0.74	0.80	0.86	0.92	0.99				
	70	16	0.72	0.78	0.85	0.91	0.97	1.04				
Td ($^{\circ}$ C)	65	24	0.48	0.54	0.59	0.65	0.71					
	65	22	0.53	0.58	0.64	0.70	0.76					
	65	20	0.57	0.63	0.69	0.75	0.81					
	65	18	0.62	0.68	0.74	0.80	0.86					
	65	16	0.66	0.72	0.78	0.85	0.91					
Td ($^{\circ}$ C)	60	24	0.43	0.48	0.54	0.59						
	60	22	0.47	0.53	0.58	0.64						
	60	20	0.51	0.57	0.63	0.69						
	60	18	0.56	0.62	0.68	0.74						
	60	16	0.61	0.66	0.72	0.78						
Td ($^{\circ}$ C)	55	24	0.37	0.43	0.48							
	55	22	0.42	0.47	0.53							
	55	20	0.46	0.51	0.57							
	55	18	0.50	0.56	0.62							
	55	16	0.55	0.61	0.66							