


## Synchronous Movement

Electric current: 230 V AC, 50 Hz



When using a 3-lead cable, connect the ground wire here.

To set the hands, use handsetter only!