# Garlock

# GYLON EPIX® Style 3510

Case Study: Colored paper production



#### **Industry** Pulp and Paper

#### Customer

International Pulp and Paper Mill

### Background

Customer is an international manufacturer of colored paper and paper boards.

### **Challenges faced**

Pumps with high vibration caused the flat face discharge flange to leak. The customer had tested many gasket types with similar results and no performance improvement. The mill was struggling with the need to change out expanded PTFE gaskets every one to two months which interrupted production with unscheduled downtime causing unnecessary costs.

# **Operating Conditions**

1. Media: White Liquor

2. Temperature: 150 °C

3. Pressure: 25 bar

4. Size: 2" Class 150 full face gasket

# **Solution and Benefits**

GYLON EPIX<sup>®</sup> Style 3510 was installed and was performing well nearly 18 months later. The gasket was replaced with the same product, GYLON EPIX<sup>®</sup> Style 3510 during regularly scheduled maintenance. By changing to GYLON EPIX<sup>®</sup> the gasket life has been extended by over 10 times that of the original expanded PTFE gaskets, saving the mill time and money from unnecessary and unscheduled down time.

For more information, please visit: **www.garlock.com** 

#### GARLOCK GMBH

an Enpro Company Falkenweg 1, 41468 Neuss, Germany +49 2131 349 0 garlockgmbh@garlock.com www.garlock.com

Garlock Sealing Technologies Garlock USA Garlock Australia Garlock Canada

Garlock China Garlock Germany Garlock India Garlock de México Garlock New Zealand Garlock Singapore