



experior

Assembly Editing	Copy assembly Ctrl + C	Cut assembly Ctrl + X	Paste assembly Ctrl + V						
	Snap assemblies Drag + Ctrl	Unsnap assemblies Ctrl + Drag	Snap fix points Shift + S						
	Multiple selection Shift + Select	Group assemblies Ctrl + G	Ungroup assemblies Ctrl + U	Alter assembly size Shift + Drag					
	Delete assembly Select + Delete	Lock / Unlock assembly Ctrl + L	Undo Ctrl + Z	Redo Ctrl + Y					
Load Control	Stop / release load on track Select + S	Jump back & release load Select + J							
	Ungroup & release load Ctrl + U	Release loads (run mode only) Cursor point + F							
					Pause / Start P	Reset model Ctrl + R	Start/stop motors Select + +	Alter motor direction Ctrl + Left Click	Run Control
					Increase time scaling Page Up	Decrease time scaling Page Down	Infinite time scaling End	Normalize time scaling Home	
					Default camera view F5	Save camera views Ctrl + Shift + 1-9	Fly to saved views 1-9	Orthogonal / isometric F12	Scene / viewing
						Toggle full screen F11	Zoom in / out + / -	Follow a load Select + F	
									Scene / details
					Lock / Unlock scene Ctrl + L	Show / Hide motors Ctrl + M	Toggle labels Ctrl + E	Toggle primitives Ctrl + P	
						Toggle shadow Ctrl + Q	Toggle anti-aliasing Ctrl + Shift + A	Debug (developer) Ctrl + Shift + D	

xcelgo