


Missing the transdisciplinary work needed for product development



- No one is responsible for the whole product development process or the whole product (solution to What)
- ⇒ Every discipline makes their own processes corresponding to their responsibility, regardless of the What
- ⇒ Planning and release management is no ones responsibility, instead only coordination follow-up, also of symptoms
- ⇒ The sub-optimization creates tremendous number of insolvable symptoms
- ⇒ Solution: PD process made from top-down transdisciplinary work, including systems design

- Functional and non-functional requirements
- Separator between the different systems designs, as well as the requirement levels