


IT Protezione contro i punti di pressione

#### Applicazione

Il punto da coprire deve essere pulito e asciutto. Tagliare la protezione PediSoft TexLine fino alla lunghezza necessaria e spostare il pezzo tagliato sul punto a rischio. Per utilizzare PediSoft TexLine come protezione per callosità, seguire le istruzioni per il ritaglio e le raccomandazioni per l'uso dal punto 1 al 3. Per ottenere una protezione individuale nei confronti dei punti di pressione, il materiale può essere ritagliato a piacere (vedere la figura 4 e 5 come esempio).

#### Nota

Se i disturbi persistono, consultare il medico o il podologo.



REF 137110

BORT. Das Plus an Ihrer Seite.

NL/BE Drukbescherming

OEKO-TEX®  
CONFIDENCE IN TEXTILES  
STANDARD 100  
D-71384 Weinstadt | www.bort.com

REF 137110-07/001 NL

BORT. Das Plus an Ihrer Seite.

CS Ochrana před otlaky

OEKO-TEX®  
CONFIDENCE IN TEXTILES  
STANDARD 100  
D-71384 Weinstadt | www.bort.com

REF 137110

BORT. Das Plus an Ihrer Seite.

PEDiSOFT Texline Druckschutz

OEKO-TEX®  
CONFIDENCE IN TEXTILES  
STANDARD 100  
D-71384 Weinstadt | www.bort.com

REF 137110

BORT. Das Plus an Ihrer Seite.



A diagram consisting of six numbered circles arranged horizontally. Circles 2 through 6 show a grey cylindrical tube being applied to a toe. Circle 1 shows the tube itself.

Pressure Protection to the required length and pull the cut piece over

the pressure-endangered area. To apply the PediSoft TexLine Pressure Protection on the ball of the foot, follow the diagram.


Protection under the law of the root, please follow the cutting instructions and application recommendations 1-3. In order to enable individual

offenen Wunden anwenden. Bei Diabetes, Entzündungen oder äußerkrankungen vor Anwendung den Arzt befragen!

In case of continuous pressure protection, the material can be cut as desired (see figs. 4 and 5 exemplarily).

In case of continuous pressure protection, the material can be cut as desired (see figs. 4 and 5 exemplarily).

#### **en contre la pression**



6  6 

rs ne se passent pas rapidement.